


Between Vega (east)
and Glenrio (west)




Alignments on this Map

Green: Original route prior to paving, which was located on the north side of the RR.

Red: First paved alignment, completed in 1937. Note that the dips showing on both portions of the map appear on 1954 aerial photos. Landergin (below) was the site of a RR siding.

Note: I-40 construction had not yet begun in this area in 1965.

Continuation of the previous map begins here.



Note:
The three drainage structures on this portion of the map are all culverts.